MATERIAL SAFETY DATA SHEET

Adapted and modified from USDL Form OSHA-20

Information on this form is furnished solely for the purpose of compliance with the Occupational Safety and Health Act and shall not be used for any other purpose. Use or dissemination of all or any part of this information for any other purpose may result in a violation of law or constitute grounds for legal action.

SECTION I	
MANUFACTURER'S NAME	EMERGENCY TELEPHONE NO.
INDUSTRIAL POLYCHEMICAL SERVICE	213-321-6515
ADDRESS (Number, Street, City, State, and ZIP Code) P.O. Box 471, 17116 So. Broadway, California S	90247
CHEMICAL NAME AND SYNONYMS Solvent Cement for ABS Plastic Pipe	TRADE NAME AND SYNONYMS WELD-ON 1707 ABS Solvent Cement
Resin-ABS and Solvent-Ketone FORM	NA NA

PAINTS, PRESERVATIVES, & SOLVENTS	%	TLV (Units)	ALLOYS AND METALLIC COATINGS	*	TLV (Units)
PIGMENTS			BASE METAL		
CATALYST None			ALLOYS		
VEHICLE Resin (Natural color)	25	_	METALLIC COATINGS		
SOLVENTS Methyl Ethyl Keton		200	FILLER METAL PLUS COATING OR CORE FLUX		
ADDITIVES			OTHERS		
OTHERS			, .		
наzardous miҳҳure	SOF	OTHER LI	QUIDS, SOLIDS, OR GASES	%	TLV (Units)
* Acrylonitrile Butadi	Lene	Styren	e		
			·		

SECT	ION III - P	PHYSICAL DATA	
BOILING POINT (°F.) Solvent - MEK	175.2	SPECIFIC GRAVITY (H2O=1) Typical	0.870±0.006
VAPOR PRESSURE (mm Hg.) @ 20°C	71.2	PERCENT, VOLATILE BY VOLUME (%) Approx.	90%
VAPOR DENSITY (AIR=1)	2,5	EVAPORATION RATE (5.7
solubility in water (of Solvent @ 20°C)	27.1		
APPEARANCE AND ODOR Milky, granslu		lium syrupy liquid - Ketone o dor	

SECTION IV - FIRE	AND EXPLOSION HAZARD DAT	Ά	
FLASH POINT (Method used)	FLAMMABLE LIMITS	Lel	Uel
(T.O.C.) 30°F		<u> </u>	<u> </u>
EXTINGUISHING MEDIA Dry chowical, Carl	on Dioxido or form type		
Prcial Fire Fighting Procedures Close or confined quarters require s		aratus. I	ouitive
pressure hose mask or airline manks	The second secon	natural property and property a	a specifical and the specifical control of t
UNUBUAL PINE AND EXPLOSION HAZARDS GOIN!	ldared fire hazard because c	f low flag	h point.
The state of the s			

0474

	SECTION V - HEALTH HAZARD DATA
THRESHOLD LIMIT VALUE	200 P.P.M
EFFECTS OF GVEREXPOSUR Severe over exposur	c e may, result in nausea, dizziness, headache, can cause narcosi
irritation of eyes	and nasal passages-normal defatting effect of solvents on tissu
EMERGENCY AND FIRST ALC	PROCEDURES VAPOR: Remove to fresh air. LIQUID: Remove contaminat
clothing and wash s	kin with water. Flush eyes with plenty of water for 15 minutes
call physician - if	swallowed, induce vomiting, CAIL PYSICIAN IMMEDIATELY.

			TION VI - REACTIVITY DATA
STABILITY UNSTABLE STABLE			conditions to Avoid Keep away from heat, sparks & flame.
		X	
INICOMENTARI	LITY (Muterials to a	roid)	
		Ammoni	ia, Caustic, Inorganic acid, Isocyanates
	DECOMPOSITION P	Ammoni	nia, Caustic, Inorganic acid, Isocyanates
	DECOMPOSITION P	Ammoni	conditions to Avoid

SECTION VII - SPILL OR LEAK PROCEDURES
steps to be taken in case material is released or spilled Eliminate all ignition source - avoid
breathing of vapor - keep liquid out of eyes. Flush with large volume of water.
WASTE DISPOSAL METHOD Incinerate - Excessive quantities should not be permitted to ent
drains where there is a danger of vapor becoming ignited.

	SECTION	VIII - SPECIAL P	ROTECTION II	NFORMATION	•
RESPIRATORY PRO	TECTION (Specify	ype/None require	with normal g. Mine Safe	ventilation.	Use respirator respirator Cat, No 459433.
VENTILATION		Provide normal		SPECIAL	459433,
	MECHANICAL /C	eneral)	per hour.	OTHER	
PROTECTIVE GLOV	1		EYE PROTECTIO	Chemical saf	ety goggles to
OTHER PROTECTIV	E EQUIPMENT			prevent spla	shing in eyes.

SECTION IX - SPECIAL PRECAUTIONS	
Keep away from heat, spark and open flame. Use with adequate ventilation, Avoid	_
prolonged breathing of vapor. Avoid contact with skin and eyes. Store between 40° and 110°F. See precautions on container label also.	
OTHER PRECAUTIONS	
FREE CONTROL OF THE PROPERTY O	

The information contained herein is based on data considered accurate. However, no warranty is expressed or implied regarding the accuracy of these data or the results to be obtained from the use thereof.

Vendor assumes no responsibility for injury to vendee or third person proximately caused by abnormal use of the material even if reasonable safety procedures are followed. Furthermore, vendee assumes the risk in his use of the material.

Page 2